



AIRFLOW PERFORMANCE, INC.
111 Airflow Drive Spartanburg, SC
29306
FAA REPAIR STATION # X9PR865N

REPAIR SPECIFICATION

REPAIR NUMBER: AP01
TITLE: Replacement of Servo Stem Seal
REVISION: 1
DATE: September 28, 2017

Effectivity:

Part Name: Fuel Servos

Models: RSA-5AD1, RSA-5AB1, RSA-10AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1,
RSA-10DB2, RSA-7AA1, RSA-7DA1

Part Number(s): All Parts List

Description of Repair: Allow Alternate Servo Stem Seal

REPAIR SPECIFICATION

REPAIR NUMBER: AP02
TITLE: Alternate 0-80 Self Locking Nut
REVISION:
DATE: October 26, 2017

Effectivity:

Part Name: Fuel Servos

Models: RSA-5AD1, RSA-5AB1, RSA-10AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1,
RSA-10DB2, RSA-7AA1, RSA-7DA1

Part Number(s): All Parts List

Description of Repair: Allow Alternate 0-80 Self Locking Nut