

AIRFLOW PERFORMANCE, INC.

111 Airflow Drive Spartanburg, SC 29306 FAA REPAIR STATION # X9PR865N

REPAIR SPECIFICATION

REPAIR NUMBER: AP01

TITLE: Replacement of Servo Stem Seal

REVISION: 1

DATE: September 28, 2017

Effectivity:

Part Name: Fuel Servos

Models: RSA-5AD1, RSA-5AB1, RSA-10AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1,

RSA-10DB2, RSA-7AA1, RSA-7DA1

Part Number(s): All Parts List

Description of Repair: Allow Alternate Servo Stem Seal

REPAIR SPECIFICATION

REPAIR NUMBER: AP02

TITLE: Alternate 0-80 Self Locking Nut

REVISION:

DATE: October 26, 2017

Effectivity:

Part Name: Fuel Servos

Models: RSA-5AD1, RSA-5AB1, RSA-10AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1,

RSA-10DB2, RSA-7AA1, RSA-7DA1

Part Number(s): All Parts List

Description of Repair: Allow Alternate 0-80 Self Locking Nut



AIRFLOW PERFORMANCE, INC.

111 Airflow Drive Spartanburg, SC 29306 FAA REPAIR STATION # X9PR865N

REPAIR SPECIFICATION

REPAIR NUMBER: AP03 TITLE: Alternate O-Ring

REVISION:

DATE: February 15, 2018

Effectivity:

Part Name: Fuel Servos

Models: RSA-5AD1,RSA-5AD2, RSA-5AB1, RSA-10AD1, RSA-10ED1, RSA-10ED2, RSA-10DB1,

RSA-10DB2, RSA-7AA1, RSA-7DA1

Part Number(s): All Parts List

Description of Repair: Allow Alternate O-rings